

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNI	TY	PE:			1				The second secon
Lined MSWLF		LCID	YW	Transfer	Co	ompost	X	SLAS	COUNTY: Forsyth
Closed MSWLF		HHW	White goods	Incin		T&P		FIRM	PERMIT NO.: SWC-34-09
CDLF		Tire T&P / Collection	Tire Monofill	Industrial Landfill	D	EMO		SDTF	FILE TYPE: COMPLIANCE

Date of Site Inspection: June 6, 2012 Date of Last Inspection: September 13, 2011

FACILITY NAME AND ADDRESS:

Overdale Large, Type 1 Solid Waste Compost Facility 4010 Old Milwaukee Lane Winston-Salem, North Carolina 27107

GPS COORDINATES: N: 36.03884 W: 80.22554

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: Jan McHargue, Solid Waste Administrator

Telephone: (336) 747-7310

Email address: janm@cityofws.org

Fax: (336) 727-8432

FACILITY CONTACT ADDRESS:

City/County Utilities
Jan HcHargue, Solid Waste Administration
Post Office Box 2511
Winston-Salem, North Carolina 27102

PARTICIPANTS:

Ricky Higgins, WRICO Equipment Corporation Charles Gerstell, NCDENR-Solid Waste Section

STATUS OF PERMIT:

A Permit to Operate a Large, Type 1 Solid Waste Compost Facility was issued to the City of Winston-Salem on October 6, 2010. This permit shall expire on October 6, 2010.

PURPOSE OF SITE VISIT:

Comprehensive Audit

STATUS OF PAST NOTED VIOLATIONS:

N/A

FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

Page 2 of 3

OBSERVED VIOLATIONS

None

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

ADDITIONAL COMMENTS

- 1. This facility is a Large, Type 1 Solid Waste Facility. Compost is produced from brush leaves, limbs, and grass clippings. Mulch and boiler fuel is produced from land clearing debris, untreated and unpainted wood, and pallets.
- 2. Temperature records were reviewed for July 2011 to June 8, 2012. Records showed that temperatures were recorded above 131°F. Multiple temperatures were observed at or near 160°F. The compost windrow should be turned when such temperatures are observed to prevent excessive heat buildup. It is recommended that future temperature logs note when the windrow is turned.
- 3. Tonnage records were reviewed from July 2011 through May 2012. Records showed that 18,714 tons of material was received during this time period.
- 4. A new office building had been placed on site since the last inspection.
- 5. Signs placed at the entrance to the facility were correct.
- **6.** A gate is located at the entrance to the facility to prevent unauthorized access.
- 7. A scale house attendant was on duty during the inspection.
- 8. A large stockpile of double-ground mulch was located on site at the time of inspection. This material was placed within a windrow south of the primary receiving area for trees and brush.
- 9. A small amount of compost material was on site at the time of inspection. Material was being ground by facility staff for placement into a compost windrow
- 10. Land clearing debris was being ground at the time of inspection. Mr. Higgins informed me that this material was being ground for boiler fuel.
- 11. No unacceptable waste streams were observed within the compost area or receiving areas during the inspection.
- 12. No significant odors were observed at the time of inspection.
- 13. No dust was observed. Site conditions were very wet due to recent heavy rains the previous night and morning prior to the inspection.
- 14. The vegetation south of the compost windrow was quite dense during the inspection preventing a thorough inspection of the area. On June 8, 2012, an email was received from Mr. Ed Gibson, Solid Waste Engineer, indicating that the aforementioned area had been moved. Thank you for your attention to this matter.
- 15. An adequate fire lane must be maintained on the north side of the mulch stockpile adjacent to the receiving area for land clearing waste. Logs from the receiving area were blocking a portion of the fire lane at the time of inspection.
- 16. All unprocessed material was being received in those areas designated on the site plan located within the approved operations plan.
- 17. Unacceptable material removed from incoming loads had been placed in the reject area as outlined in the approved operations plan. Waste consisted of 2 tires, plastic buckets, painted wood, treated lumber, metal, cardboard, carpet, and one small bag that appeared to contain household type waste. Please ensure that any household waste discovered during operations is placed in the dumpster located on site.
- 18. The facility appeared to be in compliance with all required buffers.

FACILITY COMPLIANCE INSPECTION REPORT Division of Waste Management Solid Waste Section

Page 3 of 3

Please contact me if you have any questions or concerns regarding this inspection report.

Charles T Gerstell

Environmental Senior Specialist

Regional Representative

Phone: <u>(704) 235-2144.</u>

Sent on: <u>6/11/12</u> X Email	Hand delivery	US Mail	Certified No.
---	---------------	---------	---------------

Copies: Jason Watkins, Western District Supervisor

Jessica Montie, Compliance Officer

Ed Gibson, Solid Waste Engineer - City/County Utilities